PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

NO. 63

DATE: 21/06/2025

It is certified that an inspection team headed by DMO G.B. Nagar from CMO Office inspected the GSB INTERNATIONAL SCHOOL, KAMBUXPUR DERIN, NOIDA SECTOR-151 A, on 13-06-2025 and on the basis of Water Test Report (Attached) Letter no-DMO/MAL LAB/2025/01 date-16-06-2025 Office Of The Chief Medical Officer, G.B. Nagar. certified that the GSB INTERNATIONAL SCHOOL, has safe drinking water facilities for the students and members of staff of the institution. School is also maintains the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/State/U.T.Govt.

This certificate is valid for One Year.

Shopno

Name :

Dr Narendra Kumar

Designation

: Chief Medical Officer

Name & Address of the Office/Department:.

CMO Office Sector-39 G.B Nagar

То

The Principal,
GSB INTERNATIONAL SCHOOL,
KAMBUXPUR DERIN, NOIDA SECTOR-151 A,
Gautam Budh Nagar

OFFICE OF THE CHIEF MEDICAL OFFICER-G.B. NAGAR

Ref.No:-DMO/Mal Lab/2025/63-A

Dated:-20/06/2025

WATER TEST REPORT

ADDRESS:- GSB INTERNATIONAL SCHOOL, KAMBUXPUR DERIN, NOIDA SECTOR- 151 A, G.B. NAGAR

Nil	Nil	Nil	Nil	Nil
PREVIOUS SAMPLE COLLECTION DATE	SAMPLE COLLECTION AREA	SAMPLE WATER WAS BEING USED	SAMPLE ID	RESULT

No of sample collected :- 01

SAMPLE COLLECTION DATE	SAMPLE COLLECTION AREA	SAMPLE WATER WAS BEING USED	SAMPLE ID	RESULT
13/06/2025	Borebell	Drinking	01	Satisfactory

Test Result

H2S Water Test Kit :- Satisfactory

Comments:- H2S water test kit report reflects that water having no colliforms organism.

Recommendation:- Given water is safe for drinking purpose.

Lab Technician

Malaria Lab

G.B. Nagar

DMO

G.B. Nagar

DSO

G.B. Nagar